Oil Field Environmental Incident Summary

Responsible Party: CONTINENTAL RESOURCES, INC. **Well Operator:** CONTINENTAL RESOURCES, INC.

Well Name: GRONFUR 1-28H

Field Name: BROOKLYN Well File #: 19158

Date Incident: 3/16/2014 Time Incident: 12:00 Facility ID Number:

County: WILLIAMS Twp: 155 Rng: 98 Sec: 28 Qtr: NW NE

Location Description:

Submitted By: Todd Senescall Received By:

Contact Person: Todd Senescall

PO BOX 268870

OKLAHOMA CITY, OK 73126

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Vessel Leak

Release Contained in Dike: No Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	35	Barrels	35	Barrels	35	barrels
Brine	15	Barrels	15	Barrels	15	barrels

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 9/26/2016 Clean Up Concluded: 3/18/2014

Risk Evaluation:

none

Areal Extent:

Potential Environmental Impacts:

location soil

Action Taken or Planned:

Well shut in, gasket replaced. Standing liquid sucked up, contaminated soil recovery in progress.

Wastes Disposal Location: TBD

Agencies Involved:

Updates

Date: 3/17/2014 Status: Reviewed - Follow-up Required Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill impacted the surrounding area. Followup is necessary.

Date: 3/27/2014 Status: Inspection Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location at 3/25/14.

Minimal amount of contaminant impacted areas off of location. Current remediation plans have the site being cleaned up when work is done installing a pipeline in the area that was impacted.

No followup necessary.